

Reading Room Report Sept 2024

The working group have spoken to a local roofer and engineer regarding urgent repairs to the Reading Room. The roofer has stated that the wall nearest the stream will need tying in with a steel rod to the other side before repairs to the roof can commence.



This is an example of a wall tie. Once each side of the building connected by a steel rod.

The working group have also started to look for Grants for repairs to the Reading Room as a source of funding for some of the repairs.

One member of the working group has cut the hedge and grass area around the Reading Room and uncovered concrete where a bench used to sit.