## Reading Room Report October 2024

The working group have instructed M J Fry to tie the wall in using steel. Two other companies were contacted for quotes, one refused as M J Fry had quoted first and second never came back to the working group with a quote. The cost is approx. £1000+ vat. Waiting for date when works can commence. Will aim to get a date before the meeting on 23<sup>rd</sup>.

One the wall has been tied in the missing slates can be replaced. Water has not made its way into the building yet although with the missing slates we are astonished that it hasn't yet.